

HISTORIC AMERICAN ENGINEERING RECORD

HAER  
WYO  
23-05AG.V,  
1-0

Index to Photographs

**Clay Spur Bentonite Plant and Camp, Refining Mill**  
Clay Spur Siding on the Burlington Northern  
Railroad  
4 miles northwest of Osage  
Weston County  
Wyoming

HAER No. WY-23-10

NOTE: Photographs were taken by Richard Collier, photographer, 1989

WY-23-0-1	DISTANT VIEW OF REFINING MILL, LOOKING SOUTH
WY-23-0-2	DISTANT VIEW OF REFINING MILL, LOOKING NORTHWEST
WY-23-0-3	DISTANT VIEW OF REFINING MILL, LOOKING EAST
WY-23-0-4	VIEW OF REFINING MILL, LOOKING SOUTHEAST
WY-23-0-5	VIEW OF THE UNLOADING BUILDING AT REFINING MILL, NORTHWEST SIDE
WY-23-0-6	VIEW OF THE UNLOADING BUILDING AT REFINING MILL, SOUTHEAST SIDE
WY-23-0-7	VIEW OF THE UNLOADING BUILDING AT REFINING MILL, NORTHEAST SIDE
WY-23-0-8	VIEW OF CRUDE CRUSHING AND DRYING PLANT AT REFINING MILL, LOOKING NORTHEAST
WY-23-0-9	VIEW OF STORAGE TANKS ON SOUTHEAST SIDE OF MILL, LOOKING NORTHWEST
WY-23-0-10	VIEW OF LOADING BAY ON PACKER PLANT AND WAREHOUSE, LOOKING NORTHEAST
WY-23-0-11	VIEW OF DRY STORAGE TANKS AT MILL, LOOKING SOUTH
WY-23-0-12	VIEW OF REFINING MILL, LOOKING SOUTH-SOUTHEAST
WY-23-0-13	INTERIOR VIEW OF REFINING MILL, SHOWING NO. RF-24-50 EXHAUSTER ON NO. 3 ROLL MILL, INSTALLED IN 1944. DRIED AND CRUSHED BENTONITE WAS BLOWN UP INTO A FINISHED PRODUCT BIN
WY-23-0-14	INTERIOR VIEW OF REFINING MILL, SHOWING CONVEYOR BELT IN PULVERIZING AND PACKING PLANT, LOOKING NORTH

Clay Spur Bentonite Plant and Camp,  
Refining Mill  
HAER No. WY-23-0  
Index to Photographs  
(Page 2)

- WY-23-0-15 INTERIOR VIEW OF REFINING MILL, SHOWING BASE OF FINISHED PRODUCT  
BIB. FOUR SUCH BINS ARE ALIGNED ALONG THE SOUTH SIDE OF THE  
PLANT
- WY-23-0-16 INTERIOR VIEW OF REFINING MILL, SHOWING FUEL END OF ROTARY DARBY  
DRYER IN DRYER BUILDING, LOOKING NORTHEAST
- WY-23-0-17 INTERIOR VIEW OF REFINING MILL, GIVING A SIDE VIEW OF  
45-FOOT-LONG DARBY DRYER IN DRYER BUILDING
- WY-23-0-18 INTERIOR VIEW OF REFINING MILL, SHOWING STAIRWAY LEADING TO TRACK  
HOPPER PIT THAT WAS INSTALLED IN 1941
- WY-23-0-19 INTERIOR VIEW OF REFINING MILL, SHOWING DISCHARGE END OF ROTARY  
DRYER IN DRYER BUILDING
- WY-23-0-20 INTERIOR VIEW OF REFINING MILL, SHOWING RING GEAR ON ROTARY DRYER
- WY-23-0-21 INTERIOR VIEW OF REFINING MILL, SHOWING LOCATIONS OF NOS. 1, 2,  
AND 3 MILLS, LOOKING SOUTH. SOME OF THE MACHINERY IN THIS  
SECTION HAS BEEN REMOVED.
- WY-23-0-22 INTERIOR VIEW OF REFINING MILL, SHOWING ELECTRICAL CONTROL  
PANELS LOCATED IN DRYER BUILDING